



# City of South Gate ADA Compliance Survey

USNG 11S LT 86 55



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%



— Other

Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG



# City of South Gate ADA Compliance Survey

USNG 11S LT 86 56



- Barrier**
  - × Barrier
- Curb Ramp**
  - ▲ Compliant
  - ▲ Noncompliant
- Intersection**
  - Compliant
  - Noncompliant
- Transit Stop**
  - Compliant
  - Noncompliant
- Sidewalk**
- Segment CrossSlope**
  - 0-2%
  - 2-5%
  - +5%
  - Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 86 57



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 86 58



- Barrier**
- × Barrier
- Curb Ramp**
- ▲ Compliant
  - ▲ Noncompliant
- Intersection**
- Compliant
  - Noncompliant
- Transit Stop**
- Compliant
  - Noncompliant
- Sidewalk Segment CrossSlope**
- 0-2%
  - 2-5%
  - +5%
  - Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 87 55



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 87 56



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 87 57



- Barrier**
- × Barrier
- Curb Ramp**
- ▲ Compliant
  - ▲ Noncompliant
- Intersection**
- Compliant
  - Noncompliant
- Transit Stop**
- Compliant
  - Noncompliant
- Sidewalk Segment CrossSlope**
- 0-2%
  - 2-5%
  - +5%
  - Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 87 58



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 88 55



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 88 56



- Barrier**
- × Barrier
- Curb Ramp**
- ▲ Compliant
  - ▲ Noncompliant
- Intersection**
- Compliant
  - Noncompliant
- Transit Stop**
- Compliant
  - Noncompliant
- Sidewalk Segment CrossSlope**
- 0-2%
  - 2-5%
  - +5%
  - Other

Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG











# City of South Gate ADA Compliance Survey

USNG 11S LT 88 58



## Barrier

× Barrier

## Curb Ramp

▲ Compliant  
▲ Noncompliant

## Intersection

● Compliant  
● Noncompliant

## Transit Stop

■ Compliant  
■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%  
— 2-5%  
— +5%  
— Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 89 55



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 89 56



### Barrier

× Barrier

### Curb Ramp

▲ Compliant

▲ Noncompliant

### Intersection

● Compliant

● Noncompliant

### Transit Stop

■ Compliant

■ Noncompliant

### Sidewalk

#### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 89 57



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 89 58



### Barrier

× Barrier

### Curb Ramp

▲ Compliant

▲ Noncompliant

### Intersection

● Compliant

● Noncompliant

### Transit Stop

■ Compliant

■ Noncompliant

### Sidewalk

#### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 90 55



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 90 56



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 90 57



### Barrier

× Barrier

### Curb Ramp

▲ Compliant

▲ Noncompliant

### Intersection

● Compliant

● Noncompliant

### Transit Stop

■ Compliant

■ Noncompliant

### Sidewalk

#### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 90 58



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 91 53



- Barrier**
- × Barrier
- Curb Ramp**
- ▲ Compliant
  - ▲ Noncompliant
- Intersection**
- Compliant
  - Noncompliant
- Transit Stop**
- Compliant
  - Noncompliant
- Sidewalk Segment CrossSlope**
- 0-2%
  - 2-5%
  - +5%
  - Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 91 54



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 91 55



- Barrier**
- × Barrier
- Curb Ramp**
- ▲ Compliant
  - ▲ Noncompliant
- Intersection**
- Compliant
  - Noncompliant
- Transit Stop**
- Compliant
  - Noncompliant
- Sidewalk**
- Segment CrossSlope**
- 0-2%
  - 2-5%
  - +5%
  - Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 91 56



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 91 57



### Barrier

× Barrier

### Curb Ramp

▲ Compliant

▲ Noncompliant

### Intersection

● Compliant

● Noncompliant

### Transit Stop

■ Compliant

■ Noncompliant

### Sidewalk

#### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 92 52



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 92 53



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 92 54



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 92 55



## Barrier

× Barrier

## Curb Ramp

▲ Compliant

▲ Noncompliant

## Intersection

● Compliant

● Noncompliant

## Transit Stop

■ Compliant

■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other


Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 92 56



### Barrier

× Barrier

### Curb Ramp

▲ Compliant

▲ Noncompliant

### Intersection

● Compliant

● Noncompliant

### Transit Stop

■ Compliant

■ Noncompliant

### Sidewalk

#### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 92 57



## Barrier

× Barrier

## Curb Ramp

▲ Compliant  
▲ Noncompliant

## Intersection

● Compliant  
● Noncompliant

## Transit Stop

■ Compliant  
■ Noncompliant

## Sidewalk

### Segment CrossSlope

— 0-2%  
— 2-5%  
— +5%  
— Other



Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG





# City of South Gate ADA Compliance Survey

USNG 11S LT 93 53



### Barrier

× Barrier

### Curb Ramp

▲ Compliant

▲ Noncompliant

### Intersection

● Compliant

● Noncompliant

### Transit Stop

■ Compliant

■ Noncompliant

### Sidewalk

#### Segment CrossSlope

— 0-2%

— 2-5%

— +5%

— Other

Service Layer Credits: Los Angeles County GIS, Open Street Map, Owen Group, USNG

